

PART NUMBER	DESCRIPTION
GM Domestic	
CV15.1002	CV JOINT, OUTER, PONTIAC LEMANS 1.
CV15.1003	CV JOINT, OUTER, PONTIAC LEMANS 2.
CV15.1004	CV JOINT, OUTER, PONTIAC LEMANS 1.
CV15.1007	CV JOINT, GM "J" 3.1L w/ABS 92-94,
CV15.1013	CV JOINT, OUTER,
CV15.1015	CV JOINT, OUTER, (ALL W/ABS) BUICK
CV15.1016	CV JOINT, OUTER, BUICK CENTURY COU
CV15.1017	CV JOINT, GM A J & X w/Light Duty
CV15.1019	CV JOINT, OUTER, GM A,J,N,L,X,P 85
CV15.1020	CV JOINT, GM E Class & K Class 79-
CV15.1026	CV JOINT, OUTER, (ALL w/o ABS) BUI
CV15.1030	CV JOINT, OUTER, GM "W" BODY, W/O
CV15.1032	CV JOINT, OUTER, LUMINA 2.5L 3spd.
CV15.1033	CV JOINT, OUTER,
CV15.1034	CV JOINT, OUTER, GM "C","E","H","V
CV15.1035	CV JOINT, SEVILLE 4.6L MFI 93-94
CV15.1036	CV JOINT, VARIOUS GM w/HD BRAKES 9
CV15.1037	CV JOINT, OUTER, CHEVY CORSICA 199
CV15.1038	CV JOINT, AMC EAGLE & SPIRIT 6-CYL
CV15.1042	CV JOINT, OUTER, (ALL W/ABS), BUI
CV15.1053	CV JOINT, CHEVY S-10 & BLAZER 82-9
CV15.1072	CV JOINT, CHEVY K1500 & K-2500 (3/
CV15.1082	CV JOINT, K2500 & K3500 FROM GVW 8
CV15.1091	CV JOINT, CHEVY "W" 2.22L w/ABS 92
CV15.1092	CV JOINT, 4WD K2500 & K3500 FROM 8
CV15.1092	CV JOINT, 4WD K2500 & K3500 FROM 8
CV15.1093	CV JOINT w/ABS, JEEP CHEROKEE & GR
CV15.1094	CV JOINT W/ABS, JEEP CHEROKEE & GR
CV15.1099	CV JOINT, FOR DRIVE SHAFT, JEEP
CV15.1530	CV JOINT, GM A & C Cars w/ Heavy D
Chrysler, Eagle, Hyundai, Mitsubishi	
CV30.1003	CV JOINT, COLT & CHAMP TURBO 84-88
CV30.1004	CV JOINT, COLT VISTA 4WD 85-87, SO
CV30.1009	CV JOINT, GALANT SIGMA V-6 88-89 (
CV30.1010	CV JOINT, GALANT SIGMA 3.0L 89 (10
CV30.1012	CV JOINT, OUTER, EAGLE TALON 1.8L
CV30.1015	CV JOINT, GALANT DOHC 89-91 (w/25
CV30.1016	CV JOINT, OUTER, EAGLE TALON AWD W
CV30.1018	CV JOINT, CHRYLSER w/2.2L Eng GKN
CV30.1019	CV JOINT, OUTER, CHRYSLER "G" w/AC
CV30.1026	CV JOINT, DODGE STEALTH 91-96, MIT
CV30.1028	CV JOINT, OUTER, VARIOUS CHRYSLERS
CV30.1029	CV JOINT, OUTER, MITSUBISHI GALANT
CV30.1031	CV JOINT, CARAVAN & RAM VAN, VOYAG
CV30.1033	CV JOINT, CHRYSLER 2.5L w/MAN TRAN
CV30.1038	CV JOINT, DODGE D-50 87-93, RAIDER
CV30.1039	CV JOINT, NEON 94-99 (ABS CAPABLE)
CV30.1040	CV JOINT, 104LAC, MITSUBISHI DIAMA
CV30.1045	CV JOINT, DODGE STRATUS 97-04, SEB

CV30.1049	CV JOINT, DODGE NEON (AT & MT) 200
CV30.1052	CV JOINT, HYUNDAI ACCENT w/ABS 95-
CV30.1055	CV JOINT, ECLIPSE 2.4L w/AT 2000-0
CV30.1059	CV JOINT, HYUNDAI SONATA 2.4L 99-0
CV30.1060	CV JOINT, CHRYSLER, DODGE, PLYMOUT
CV30.1062	CV JOINT, HYUNDAI ATOS 1.0L 99-03
CV30.1066	CV JOINT, HYUNDAI ELANTRA 1.6L DOH
CV30.1067	CV JOINT, OUTER, EAGLE SUMMIT 1.5L
CV30.1069	CV JOINT, EAGLE & RENAULT MEDALLIO
CV30.1072	CV JOINT, EAGLE PREMIER 3.0L 88-92
CV30.1077	CV JOINT, EAGLE SUMMIT 1.5L 93-95,
CV30.1080	CV JOINT, DODGE DAKOTA 4WD 91-96 w
CV30.1081	CV JOINT, DAKOTA & DURANGO 98-99
CV30.1082	CV JOINT, DAKOTA & DURANGO 2000-20
CV30.1086	CV JOINT, CHRYSLER w/SAGINAW Desig
CV30.1090	CV JOINT, DODGE INTREPID 96-97 w/A
CV30.1095	CV JOINT, MONTERO 3.5L 92-97, 3.0L
CV30.1099	CV JOINT, INTREPID, CONCORDE & VIS
CV30.1100	CV JOINT, MITSUBISHI LANCER 1.6L C
CV30.1160	CV JOINT, OUTER, HYUNDAI ELANTRA 1
CV30.1235	CV JOINT, ECLIPSE 2.0L w/AT 1999 w
CV30.1541	CV JOINT, CHRYSLER w/Citroen 84-86
CV30.4029	CV JOINT, HYUNDAI (Special Order -
CV30.4033	CV JOINT, MITSUBISHI - Special Ord

Ford, Lincoln, Mercury

CV35.1012	CV JOINT, FORD ASPIRE w/MAN TRANS
CV35.1023	CV JOINT, KIA FESTIVA (EXPORT MODE
CV35.1025	CV JOINT, TAURUS 3.0L V8 90-95, 3.
CV35.1029	CV JOINT, FORD ASPIRE 94-97 w/AUTO
CV35.1047	CV JOINT, FOCUS SOHC w/MT 2000-200
CV35.1048	CV JOINT, FOCUS DOCH w/MT 2000-02,
CV35.1049	CV JOINT, OUTER, T-BIRD ALL MODELS
CV35.1050	CV JOINT, FORD TEMPO 3.0L Auto Tra
CV35.1055	CV JOINT, FORD TEMPO 2.3L Auto Tra
CV35.1060	CV JOINT, FORD CONTOUR & MERCURY M
CV35.1062	CV JOINT, FORD
CV35.1065	CV JOINT, FORD CONTOUR & MERCURY M
CV35.1070	CV JOINT, FORD AEROSTAR AWD 4/91-9
CV35.1080	CV JOINT, FORD EXPLORER 4.0L 95-00
CV35.1085	CV JOINT, FORD F-150 97-00, EXPEDI
CV35.1090	CV JOINT, OUTER, ESCORT 1.8L & 1.9
CV35.1099	CV JOINT, FOR DRIVE SAHFT, FORD EX
CV35.1149	CV JOINT, INNER, T-BIRD (FITS 8.8
CV35.1194	CV JOINT, FORD TAURUS & MERCURY SA
CV35.1934	CV JOINT, OUTER, FORD ESCORT 86-90

Toyota, Daihatsu, Lexus, Chevy Nova

CV40.1001	CV JOINT, COROLLA w/o ABS
CV40.1007	CV JOINT, STARLET 86-88 (l'ntl Mod
CV40.1008	CV JOINT, CELICA GTS 86-89
CV40.1010	CV JOINT, CAMRY89-91 U.S. Mfg, 88
CV40.1011	CV JOINT, CELICA GT & GTS 5FE 90-9

CV40.1012	CV JOINT, DAIHATSU, MALAYSIA MODEL
CV40.1013	CV JOINT, DAIHATSU CHARADE w/MT 88
CV40.1014	CV JOINT, OUTER, DAIHATSU CHARADE
CV40.1017	CV JOINT, DAIHATSU G100 w/54MM SEA
CV40.1018	CV JOINT, DAIHATSU G12 TURBO, APPL
CV40.1019	CV JOINT, DAIHATSU G10, G11 83-85
CV40.1021	CV JOINT, CAMRY 3SFE 4-Cyl 4WD w/M
CV40.1023	CV JOINT, (w/ABS),CAMRY 3VZFE 3.0L
CV40.1026	CV JOINT, COROLLA 4AFE & 7AFE 93-0
CV40.1027	CV JOINT, STARLET EP 80 1.0L (INTE
CV40.1029	CV JOINT, TOYOTA COROLLA 1.5L, 200
CV40.1030	CV JOINT, TOYOTA PRADO (INTL) 3.0L
CV40.1032	CV JOINT, CAMRY 2.2L GKN 94-00 w/A
CV40.1033	CV JOINT, TOYOTA COROLLA 1.6L (INT
CV40.1040	CV JOINT, TERCEL 91-94 (w & w/o AB
CV40.1045	CV JOINT, TERCEL 95-97
CV40.1050	CV JOINT, OUTER, TOYOTA ECHO w/ABS
CV40.1051	CV JOINT, TOYOTA YARIS (ECHO)
CV40.1054	CV JOINT, TOYOTA CAMRY 4CYL W/ABS,
CV40.1057	CV JOINT, LEXUS 470, 98-05
CV40.1061	CV JOINT, PASEO 92-98 (w & w/o ABS
CV40.1070	CV JOINT, TOYOTA TACOMA 4WD 95-00
CV40.1078	CV JOINT, TOYOTA RAV-4 4WD 96-00 (
CV40.1079	CV JOINT, TOYOTA RAV-4 2WD 96-97 (
CV40.1080	CV JOINT, TOYOTA AVALON 97-01 (w/A
CV40.1081	CV JOINT, TOYOTA CAMRY 6 CYL
CV40.1082	CV JOINT, TOYOTA CAMRY 2004
CV40.1085	CV JOINT, CAMRY 3.0L V6 92-94 (JAP
CV40.1086	CV JOINT, CAMRY V-6 2002-03 (W/ABS
CV40.1093	CV JOINT, 4WD PICK-UP 79-85, LANDC
CV40.1094	CV JOINT, TOYOTA LANDCRUISER 4.5L
CV40.1095	CV JOINT, 4-RUNNER 86-95 w/o ABS;
CV40.1096	CV JOINT, LANDCRUISER 91-94, 99-On
CV40.1097	CV JOINT, 4-RUNNER 96-On
CV40.6021	CV JOINT, INNER, (Pancake Type) CA

Acura, Honda

CV50.1001	CV JOINT, CRX 1300HF & 1500HF 84-8
CV50.1003	CV JOINT, ACCORD 76-80, CIVIC 73-8
CV50.1004	CV JOINT, ACCORD 81-83 (W/45mm Sea
CV50.1005	CV JOINT, PRELUDE 81-82, ACCORD 81
CV50.1006	CV JOINT, PRELUDE 83-87, ACCORD 82
CV50.1009	CV JOINT, CVCC 1500cc 5-SPEED 84-8
CV50.1011	CV JOINT, ACCORD SEi 85, PRELUDE S
CV50.1015	CV JOINT, CIVIC CVCC 1300 84-87, 1
CV50.1016	CV JOINT, ACCORD 86-89, ACCORD w/F
CV50.1017	CV JOINT, HONDA CIVIC DX & LX 88-9
CV50.1019	CV JOINT, ACCORD 90-97, PRELUDE 90
CV50.1021	CV JOINT, ACURA LEGEND 87-90 w/88m
CV50.1027	CV JOINT, LEGEND 91-95 V-6
CV50.1029	CV JOINT, PRELUDE 2.2L 93-96, 2.3L
CV50.1030	CV JOINT, CIVIC DEL SOL 1.6L V-TEC

CV50.1035	CV JOINT, CIVIC 1.5L & 1.6L 92-00
CV50.1040	CV JOINT, HONDA ODDYSSEY 1999-2002
CV50.1050	CV JOINT, ACURA TL 2.5L 95-98 w/AB
CV50.1059	CV JOINT, OUTER, ACCORD 4 CYL 2003
CV50.1060	CV JOINT, ACURA VIGOR 92-94 w/ABS
CV50.1065	CV JOINT, HONDA CRV w/Auto Trans 1
CV50.1069	CV JOINT, OUTER, ACCORD 6-CYL 2003
CV50.1092	CV JOINT, HONDA CIVIC 99-ON w/ABS
CV50.1093	CV JOINT, CIVIC 2001-On (ABS Ready

Infiniti, Nissan

CV60.1003	CV JOINT, PULSAR & SENTRA (NON-TUR
CV60.1004	CV JOINT, SUNNY 1.3L 82-84, PULSAR
CV60.1006	CV JOINT, PULSAR DOHC 87-90, SENTR
CV60.1007	CV JOINT, NISSAN BUCAT, FEELING 1.
CV60.1009	CV JOINT, BLUEBIRD 1.8L (Int'l Mod
CV60.1011	CV JOINT, SENTRA SOHC 87-90, PULSA
CV60.1015	CV JOINT, NISSAN MARCH & MICRA 84-
CV60.1020	CV JOINT, SUNNY (INT'L) 91-94
CV60.1022	CV JOINT, NISSAN SENTRA 1.6L 91-99
CV60.1025	CV JOINT, PULSAR TURBO 87-On
CV60.1026	CV JOINT, (ABS READY) MAXIMA 85-91
CV60.1027	CV JOINT, MAXIMA DOHC 92-99 w/ABS
CV60.1029	CV JOINT, MAXIMA DOHC 92-94 w/ABS
CV60.1032	CV JOINT, NISSAN TSURU III 92-95 (
CV60.1033	CV JOINT, SUNNY BM10 93-On (Int'l
CV60.1035	CV JOINT, SENTRA 2.0L 91-94, NX 91
CV60.1037	CV JOINT, NISSAN
CV60.1040	CV JOINT, ALTIMA 1994-2001 (w & w/
CV60.1043	CV JOINT, OUTER, NISSAN ALTIMA 2.5
CV60.1044	CV JOINT, NISSAN ALTIMA 3.5 W/ABS
CV60.1050	CV JOINT, NISSAN QUEST & MERCURY V
CV60.1058	CV JOINT, NISSAN 200SX 2.0L & SENT
CV60.1060	CV JOINT, INFINITI G20 91-96 w/ABS
CV60.1088	CV JOINT, HARDBODY 87-89, HARDBODY
CV60.1098	CV JOINT, HARDBODY 6-Cyl 90-95, PA
CV60.1109	CV JOINT, PRIMERA (Int'l Models),
CV60.1712	CV JOINT, NISSAN TSURU II 88-92 IN

Subaru

CV70.1001	CV JOINT, SUBARU, FRONT WHEEL DRIV
CV70.1002	CV JOINT, 1600 1800 4WD 72-84, BRA
CV70.1003	CV JOINT, 2WD HB 85-89, LOYALE, SE
CV70.1004	CV JOINT, SEDAN WAGON COUPE COUPE
CV70.1005	CV JOINT, Loyale Sedan & Wagon Tur
CV70.1007	CV JOINT, SUBARU XT-6 2WD 2.7L 88-
CV70.1008	CV JOINT, SUBARU LEGACY 2WD 89-3/9
CV70.1010	CV JOINT, LEGACY 4WD 89-10/90, IMP
CV70.1011	CV JOINT, SUBARU JUSTY 700cc
CV70.1012	CV JOINT, LEGACY w/4WD 11/90-95, 2
CV70.1013	CV JOINT, SUBARU FORRESTER 98-02 W
CV70.1015	CV JOINT, SUBARU XT-6 4WD 88-91
CV70.1016	CV JOINT, JUSTY 89-94

CV70.1018	CV JOINT, SUBARU J-10 (Int'l Model
CV70.1019	CV JOINT, SUBARU JUSTY 87-88
CV70.6012	CV JOINT, INNER, SUBARU LEGACY 2.0

Chevy Luv, Isuzu

CV75.1004	CV JOINT, SPECTRUM & I-MARK 84, SP
CV75.1006	CV JOINT, SPECTRUM & I-MARK 84, I-
CV75.1009	CV JOINT, ISUZU I-MARK TURBO 87-89
CV75.1031	CV JOINT, OUTER, ISUZU TURBO 82-87
CV75.1051	CV JOINT, OUTER, ISUZU P'UP 89-94,
CV75.1061	CV JOINT, ISUZU AMIGO 1998-2000
CV75.1071	CV JOINT, ISUZU RODEO 1996-2000
CV75.1081	CV JOINT, ISUZU 4WD P'UP 1998-2002

Mazda, Ford Imports

CV80.1001	CV JOINT, 323 & GLC 1300 & 1500 81
CV80.1002	CV JOINT, 626 10/82-87
CV80.1011	CV JOINT, OUTER, MAZDA 626 Turbo 8
CV80.1012	CV JOINT, MILLENNIA 2300cc 96-98 (
CV80.1014	CV JOINT, (All w/ABS) FORD PROBE 2
CV80.1016	CV JOINT w/ABS, MAZDA MX6 2.0L M/T
CV80.1018	CV JOINT, MAZDA MX6 & 626 2.5L w/A
CV80.1020	CV JOINT, MAZDA B2600 P'UP 4WD 87-
CV80.1021	CV JOINT, OUTER, MAZDA MILLENNIA 2.
CV80.1025	CV JOINT, PROTEGE 1.6L 1999-2002 w
CV80.1028	CV JOINT, MAZDA MPV 2002-03
CV80.1035	CV JOINT, PROTEGE 1.8L & 2.0L 1999
CV80.1037	CV JOINT, MX3 90-93 (NSK Design w/
CV80.1050	CV JOINT, MPV 3.0L 89-95
CV80.1069	CV JOINT, FORD TELSTAR 1.6L & 1.8L
CV80.1108	CV JOINT, PROTEGE 1.5L 96-98 w/ABS
CV80.1110	CV JOINT, MX3 92-95, PROTEGE 95-98

Geo, Daewoo, Suzuki

CV85.1001	CV JOINT, BLMC ROVER MINI 850 & 11
CV85.1010	CV JOINT, GEO STORM GSI DOHC w/AT
CV85.1012	CV JOINT, GEO STORM GSI, DOHC w/MT
CV85.1015	CV JOINT, RIGHT SIDE, GEO STORM SO
CV85.1016	CV JOINT, LEFT, GEO STORM SOHC 90-
CV85.1017	CV JOINT, SUZUKI FRONTE, ALTO, CER
CV85.1022	CV JOINT, OUTER, SUZUKI SWIFT 81-8
CV85.1024	CV JOINT, SUZUKI SWIFT SOHC w/AT &
CV85.1025	CV JOINT, SUZUKI SIDEKICK 89-99, G
CV85.1026	CV JOINT, SUZUKI SWIFT w/DOHC 89-9
CV85.1027	CV JOINT, SUZUKI ESTEEM 95-00 w/AB
CV85.1030	CV JOINT, OUTER, SUZUKI SWIFT 1.6L
CV85.1037	CV JOINT, SUZUKI ESTEEM 95-00 (w/2
CV85.1040	CV JOINT, SUZUKI GRAND VITARA w/Au
CV85.1045	CV JOINT, SUZUKI GRAND VITARA w/Ma
CV85.1047	CV JOINT, SUZUKI
CV85.1050	CV JOINT, KIA SEPHIA 1.8L 95-98, M
CV85.1054	CV JOINT, GEO METRO 1.3L 95-00 w/A
CV85.1057	CV JOINT, KIA SEPHIA 1.6L SOHC 94-
CV85.1060	CV JOINT w/ABS, KIA SEPHIA 1.6L 98

CV85.1062	CV JOINT, KIA RIO 2001-02 W/ABS
CV85.1208	CV JOINT, ALTO
CV85.1214	CV JOINT, ALTO 660 CN215
CV85.1215	CV JOINT, BALENO 1.3L, JAMAICA
CV85.1236	CV JOINT, OUTER, DAEWOO TICO PM 90
CV85.1249	CV JOINT, DAEWOO LEGANZA 2.0L DOHC
CV85.1501	CV JOINT, LANDROVER DISCOVERY & RA

Audi, Volkswagen

CV90.0911	CV JOINT, Inner, Passat 1.8 Turbo
CV90.1504	CV JOINT, Audi 90 Quattro 2.3L 90-
CV90.1505	CV JOINT, Audi 100 Quattro 2.8L 91
CV90.1510	CV JOINT, AUDI 90 2.8L 93-00 w/ABS
CV90.1515	CV JOINT, OUTER, AUDI 100 QUATTRO
CV90.1801	CV JOINT, Outer, Dasher 74-81, Aud
CV90.1802	CV JOINT, Outer, Rabbit 75-80, Jet
CV90.1804	CV JOINT, OUTER, AUDI A4 1.6L,1.8L
CV90.1805	CV JOINT, VW CABRIOLET 82-84, GOLF
CV90.1807	CV JOINT, OUTER, Cabriolet 85-93,
CV90.1808	CV JOINT, Inner, VW TYPE 2 w/Doubl
CV90.1809	CV JOINT, VW, Type I & III w/Doubl
CV90.1811	CV JOINT, Outer, w/ABS, Rear: 4000
CV90.1812	CV JOINT, Outer, Audi 5000 Gas 78-
CV90.1814	CV JOINT, PASSAT V6 98-2001, AUDI
CV90.1815	CV JOINT, OUTER, w/o ABS, 4000 Qu
CV90.1816	CV JOINT, PASSAT VR6 2.8L 92-97, C
CV90.1820	CV JOINT, OUTER, NEW BEETLE 98-00
CV90.1822	CV JOINT, Outer, VW Fox 87-92, Qua
CV90.1824	CV JOINT, OUTER, Audi A4 1.8 Turbo
CV90.1829	CV JOINT, Outer, Quantum/5 M/T 84-
CV90.1830	CV JOINT, OUTER, AUDI A4 QUATTRO A
CV90.1835	CV JOINT, OUTER, AUDI QUATTRO 1.8
CV90.1855	CV JOINT, VW TRANSPORTER 1.9L, 23.

Fiat, Saab, Saturn, Sterling, Volvo

CV95.1002	CV JOINT, FIAT UNO, PREMIO, RITMO,
CV95.1003	CV JOINT, OUTER, SAAB 99 GL 82-84,
CV95.1004	CV JOINT, SAAB 900 1988-93 w/ABS
CV95.1006	CV JOINT, SAAB 9000 w/o ABS 86-98
CV95.1032	CV JOINT, FIAT PALIO 1.6L, PALIO W
CV95.1040	CV JOINT, FIAT PALIO 1.0, 1.1 & 1.
CV95.1050	CV JOINT, SATURN w/o ABS 91-93
CV95.1051	CV JOINT, SATURN w/ABS 91-93
CV95.1052	CV JOINT, SATURN w/o ABS 94-99
CV95.1053	CV JOINT, SATURN w/ABS 94-99
CV95.1083	CV JOINT, VOLVO 850 93-97, C70 S70
CV95.1084	CV JOINT, VOLVO 850 93-97, C720 S7
CV95.1088	CV JOINT, STERLING 825SL w/ & w/o